



1500 Brigantine Drive  
Coquitlam, BC, V3K 7C1

Telephone: 604-520-3321  
Facsimile: 604-524-9186  
www.intertek.com

March 14, 2013

New Project No. G101108924  
Original Project No. 3101100

Jay Song  
Good Morning Enterprises Inc.  
#104 – 185 Forester Street  
North Vancouver, BC  
V7H 0A6

Ph: 604-904-7866  
Fax: 604-904-7848  
email: jay@gmcanada.com

**Subject: Findings Report 101108924COQ-001B**

Dear Mr. Song


Intertek has conducted a spot (stain resistance) test for Good Morning Enterprises Inc. in accordance with the client's test specifications. Samples were submitted to the Evaluation Center on July 19, 2006 and were identified as Imperastone, a polished granite stone with embedded color. 10 mm diameter drops of ABC laundry soap slurry, hydrochloric acid of pH 3 and liquid bleach were placed on the surface of the test samples. The prepared samples were left undisturbed in a room maintained at  $23 \pm 2^{\circ}\text{C}$  and relative humidity of  $50 \pm 5\%$  for 72 hours. After the 72 hour period, the agent was removed with distilled water and the samples were left to dry. A visual examination was then performed to determine any permanent staining. The results of testing can be found in the table below.

Table 1. Test Results	
Test Description	Results
Spot (Stain Resistance) Test	No sign of any change

If there are any questions regarding the results contained in this report, or any of the other services offered by Intertek, please do not hesitate to contact the undersigned.

Completed by: Chris Chang, EIT  
Test Technician  
Building Products

Title:  
Signature:



Reviewed by: Baldeep Sandhu  
Technologist  
Building Products

Title:  
Signature



This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only the sample tested. This report by itself does not imply that the material, product or service is or has ever been under an Intertek certification program.

## **APPENDIX A: Test Data (1 page)**

---



# Spot Test

**Date:** Aug. 11/06  
**Client:** Good Morning Enterprises Inc.  
**Proj. #:** 3101100  
**Product Tested:** Polished Granite Stone  
**Tech:** G. Nishio  
**Reagents used:** ABC Laundry soap mixed with just enough water to make slurry  
pH 3 HCl  
Liquid bleach  
**Exposure period:** 1 Hour total  
**Test Method:** A line of reagent placed across surface of sample  
Reagent left on sample for one hour  
After one hour, reagent washed off.  
**Ambient conditions:** 23°C RH 51%  
**Samples tested:** 1) Brown  
2) Red

### Comments/Observations @ 2 hour inspection

Sample #	Reagent used		
	ABC Laundry soap	pH 3 HCl	Liquid Bleach
1	No stain or discolouring	Noticeable dark stain at spot points	Very faint stain spot at spot points
2	No stain or discolouring	Noticeable dark stain at spot points	Very faint stain spot at spot points

### Comments/Observations @ 72 hour inspection

Sample #	Reagent used		
	ABC Laundry soap	pH 3 HCl	Liquid Bleach
1	No stain or discolouring	No stain or discolouring	No stain or discolouring
2	No stain or discolouring	No stain or discolouring	No stain or discolouring

Note:

Samples inspected by G. Nishio  
B. Sandhu  
T. Kwasnycia